

CLASSIFIED MESSAGE

MFG. 6-63

Approved For Release 2000/05/04 : CIA-RDP66B00664R000400090030-5

DATE 0036Z 13 MAR 64

S E C R E T

ROUTING

2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO : DIRECTOR

25X1A

FROM :

ACTION:

INFO :

OPS 1-12

PRIORITY

TOR 0137Z 13 MAR 64

IN 67490

TO PRIORITY

0156

A. S014A

B. B/119/10,500/ASPIC

C. HTA-3B/D-19/2/75 DEGREES

D. MAC NR 1, 2.22 - 2.34/MAC NR 2, 2.23 - 2.18

E. 8402/9L - 247-5-10-11-3/9R - 247-13-11-3

F. (1) GOOD

(2) GOOD

(3) POOR

(4) FAIR

(5) GOOD

(6) FAIR

(7) OPERATIVE GOOD

G. TAKE RECEIVED 12/0015Z MAR IN COVERED STEEL BOXES. BOLTS NOT SECURED WITH SEALS. DATA CHAMBER CLOCK SET FOR PLUS FOURTEEN HOURS ZULU. MANUFACTURER'S SPLICE ON FRAMES 0291 AND 2876/9L AND 1502/9R. CAMERA METERING MALFUNCTION FRAME 0009 AND 0011/9L. STATIC ELEC IN

CONTINUED

S E C R E T

GROUP 1
Excluded from automatic
downgrading and
declassification

Approved For Release 2000/05/04 : CIA-RDP66B00664R000400090030-5

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

25X1A

0156 (IN 67490)

S E C R E T

PAGE TWO

FRAME 0007/9L AND INTERMITTENTLY BETWEEN FRAMES 0800 - 1000/9L. VACUUM OR PRESSURE MARKS THROUGHOUT 9L (GEAR-TYPE MARKS ALONG DATA CHAMBER EDGE AND ALONG TITLING EDGE). ELEVATOR ROLLER MALFUNCTION ON HTA-3B (318) CAUSED SEVERE ABRASIONS, FILM TEARS, AND ABNORMAL DEVELOPING STREAKS FROM FRAMES 2260 TO 2390/9R. FILM REMOVED FROM PROCESSOR AND DEVELOPED BY HAND. CIRCUIT BREAKER OVERLOAD AND SMALL ELECTRICAL FIRE IN DRYER OF HTA-3B (317) FRAMES 2828/9L ONLY FRAMES COMPLETELY DAMAGED. SEVERAL CREASES FROM MIDDLE TO END OF BOTH 9L AND 9R. DARKROOM CUT MADE AT 3225/9L.

H. DEPARTURE OF TAKE TENTATIVELY PLANNED TO DEPART 14 MAR 64.

END OF MESSAGE

S E C R E T